

5-Step Supplier Quality Checklist

Want to take control of your supplier network? Follow these 5 steps to improve your supplier ecosystem and get the best possible quality from your suppliers at the lowest risk.

1



Extend Supplier Network Visibility

Gain visibility into your supplier network with audits, CoAs & CoCs, third-party certifications, and vendor performance tracking tools.

2



Rate and Scorecard Suppliers

Define criteria for maintaining approved status, communicate expectations, and grade performance with scorecarding. Incorporate criteria into POs and SOPs.


3



Automate Reminders and Improve Supplier Communication

Scale your supplier management efficiently with an automated system to gain more control of your supplier network with less effort.

4



Build Supplier Risk Models

Define your risk assessment criteria, develop a risk scoring system, set thresholds, triggers & alerts, and establish a plan for failures.

5



Continuous Monitoring

Monitor performance continuously to address issues sooner. Add incidents to scorecards, and issue corrective actions to minimize risks and fix root causes.